














OpenMV Cam H7 Plus

PINOUT

| | |
|---|------------------|
|  | Power |
|  | GND |
|  | OpenMV pin name |
|  | Analog input |
|  | SPI |
|  | UART |
|  | I ² C |
|  | CAN |
|  | Servo |
|  | DAC |
|  | Spec Pins |
|  | PWM |



All GPIO pins support interrupts



All GPIO pins 5V tollerant, unless pin P6